ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

**BBMP ENGINEERING DEPARTMENT**

**Road History Data Sheet**

## General

**Zone**
YELAHANKA

**Ward No.**
3

**Ward Name**
Atturu

**Street ID**
W0277, W0229, W0160, W0283, W0237, W0876, W0291, W

**Street Name**
NA, Ambedkar Nagar Slum, Maheshwari Nagar Opp Police Station Rd

**Significant Landmark**
Muneshwara layout 1st main and cross roads

**Segment No.**
3/C-W0277/S105518

**Total Length (m)**
483.90

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 483.90 | 77.562940 | 13.105129 | 77.566595 | 13.103974 | W0299 | W0223 |

## Work Details

**History of Road / Lane / Circles**

**Name of the Work**
Asphalting to Roads and Improvements to Drain in Muneshwara layout 1st main and cross roads in ward no 03 Yelahanka Satellite Town Sub division Yelaha

**Sanctioned Estimated Amount (Rs.)**
4500000

**Sanctioned Year**
2017

**Year**
2017 - 2018

**Type of Work**
Asphalting

**Other Work Type**

**Tender**
Not a Tender

**Work Details**
Asphalting to Roads and Improvements to Drain in Muneshwara layout 1st main and cross roads in ward no 03 Yelahanka Satellite Town Sub division Yelahanka zone

**Job No. / Work Code**
003-17-000010

**Work Order No.**
BBMP/EE (YNK.D) /WO/142/2017 -18

**Work Order Date**
31/03/2017

**Period of Extention**
90 DAYS

**Defect Liability Period From**
30/04/2017

**Defect Liability Period To**
29/04/2018

**Multiple road involved with the same Job No/ Work Code #**
Yes

## Contractor Details

**Name of Contractor**
KRIDL

**Contractor Reg No (BBMP/PWD)**

**Expenditure Booked \ Released (Rs)**
0.00

**Phone No.**

**E-Mail ID**

## Field Inspection Details

**Number of Trees**

6

**Any Other Information**

**Name**

CHANDRAKANTH

**Date of Inspection**

24/05/2017

**Remarks**

COMPLETED

| Category | Image | Photo Remark |
|---|---|---|
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |

**Zone:** YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0277, W0229, W0160, W0283,

| | | |
|---|---|---|
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |
| Road Condition | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | PARAMESHWARAIAH | 24/05/2017 | 23/06/2017 | COMPLETED |
| SE | VASU K M | 24/05/2017 | 23/06/2017 | COMPLETED |
| EE | VASU K M | 24/05/2017 | 23/06/2017 | COMPLETED |
| AEE | ASHOK | 24/05/2017 | 23/06/2017 | COMPLETED |
| AE | CHANDRAKANTH | 24/05/2017 | 23/06/2017 | COMPLETED |
| AE | CHANDRAKANTH | 24/05/2017 | 23/06/2017 | COMPLETED |

**Zone:** YELAHANKA **Ward No:** 3 **Ward Name:** Alturu **Street ID:** W0277, W0229, W0160, W0283,